

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 07/23/2015
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155635	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01, 03 B. WING _____		(X3) DATE SURVEY COMPLETED 07/20/2015
NAME OF PROVIDER OR SUPPLIER GRACE VILLAGE HEALTH CARE FACILITY			STREET ADDRESS, CITY, STATE, ZIP CODE 337 GRACE VILLAGE DR WINONA LAKE, IN 46590		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 000	<p>INITIAL COMMENTS</p> <p>A Life Safety Code Recertification and State Licensure Survey was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).</p> <p>Survey Date: 07/20/15</p> <p>Facility Number: 000501 Provider Number: 155635 AIM Number: 100266260</p> <p>At this Life Safety Code survey, Grace Village Health Care Facility was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire, the 2000 edition of National Fire Protection Association (NFPA) 101, Life Safety Code (LSC) and 410 IAC 16.2. The original building consisting of halls 1, 2, 3, 5 and the main dining room was surveyed with Chapter 19 Existing Health Care Occupancies.</p> <p>This one story facility was determined to be of Type III (211) construction and was fully sprinklered. The facility has a fire alarm system with smoke detection in corridors and in areas open to the corridors. Battery operated smoke detectors were installed in all resident rooms in the original building. The facility has a capacity of 89 and had a census of 87 at the time of this survey.</p> <p>All areas where the residents have customary access were sprinklered. Areas providing facility services which were not sprinklered included a detached garage used for storage of maintenance equipment and parts with the</p>	K 000			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 07/23/2015
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155635	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01, 03 B. WING _____		(X3) DATE SURVEY COMPLETED 07/20/2015
NAME OF PROVIDER OR SUPPLIER GRACE VILLAGE HEALTH CARE FACILITY			STREET ADDRESS, CITY, STATE, ZIP CODE 337 GRACE VILLAGE DR WINONA LAKE, IN 46590		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K 000	Continued From page 1 portion of the building used as a maintenance garage, and a detached shed used for storage of parts and lawn equipment. The facility had a fire pump room that was sprinklered.	K 000			
K 000	INITIAL COMMENTS A Life Safety Code Recertification and State Licensure Survey was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a). Survey Date: 07/20/15 Facility Number: 000501 Provider Number: 155635 AIM Number: 100266260 At this Life Safety Code survey, Grace Village Health Care Facility was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire, the 2000 edition of National Fire Protection Association (NFPA) 101, Life Safety Code (LSC) and 410 IAC 16.2. The Rehabilitation hall and Therapy was surveyed with Chapter 18 New Health Care Occupancies. The Rehabilitation addition to the facility, completed in 2007, was determined to be of Type V (000) construction and fully sprinklered. The facility has a fire alarm system with smoke detection in corridors and in areas open to the corridors. The new Rehabilitation Unit had hard wired smoke detectors in resident rooms. The facility has a capacity of 89 and had a census of 87 at the time of this survey. All areas where the residents have customary	K 000			

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 07/23/2015
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155635	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01, 03 B. WING _____		(X3) DATE SURVEY COMPLETED 07/20/2015
NAME OF PROVIDER OR SUPPLIER GRACE VILLAGE HEALTH CARE FACILITY			STREET ADDRESS, CITY, STATE, ZIP CODE 337 GRACE VILLAGE DR WINONA LAKE, IN 46590		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 000	Continued From page 2 access were sprinklered. Areas providing facility services which were not sprinklered included a detached garage used for storage of maintenance equipment and parts with the portion of the building used as a maintenance garage, and a detached shed used for storage of parts and lawn equipment. The facility had a fire pump room that was sprinklered.	K 000			